

openQA Tests - action #15230

aarch64 worker overdrive2 shows unexpected uefi shell now

2016-12-02 20:08 - okurz

Status:	Resolved	Start date:	2016-12-02
Priority:	Immediate	Due date:	
Assignee:	asmorodskyi	% Done:	0%
Category:	Infrastructure	Estimated time:	0.00 hour
Target version:			
Difficulty:			
Description			
Observation			
see https://openqa.suse.de/tests/655130/modules/bootloader_uefi/steps/3 , reproducible			
Reproducible			
Fails since two jobs, probably because something on the worker side changed			
Expected result			
Last good: here			
Further details			
Always latest result in this scenario: latest			
Related issues:			
Related to openQA Tests - action #15178: Permanent boot order with bootindex		Resolved	2016-12-01
Related to openQA Tests - action #18380: [qam] test fails in bootloader_uefi ...		Resolved	2017-04-06

History

#1 - 2016-12-03 11:52 - okurz

- Related to action #15178: Permanent boot order with bootindex added

#2 - 2016-12-04 11:32 - dirkmuller

On request of Jozef Pupava I've installed the uefi update from SLE12 SP2 with the fix from https://bugzilla.suse.com/show_bug.cgi?id=1009707 installed. as expected this UEFI code does not work at all (as was known already before). I can revert to a working UEFI firmware though.

It is known that the SP2 firmware is completely broken thats why we never used it so far.

#3 - 2016-12-05 09:16 - dzedro

I reverted to the working firmware on overdrive2

#4 - 2016-12-07 15:15 - asmorodskyi

- Status changed from New to In Progress

- Assignee set to asmorodskyi

#5 - 2016-12-08 08:58 - asmorodskyi

- Status changed from In Progress to Resolved

not seeing issues for 3 executions in 2 different builds .

#6 - 2017-04-18 12:56 - okurz

- Related to action #18380: [qam] test fails in bootloader_uefi - aarch64 added